

LIBRARY							
Power Sockets	5		All Tested	Anthony Bailey			Extension lead but will be monitored and PAT tested
Curtains flameproofed	2						
UPPER ROOM							
Low side beams	4		Notice attached to avoid banging head	AB			Notice in place
Power Sockets	5			Anthony Bailey			
Stair gate	3		Flameproof fabric of curtains. Fitted for storage.	Anthony Bailey			**Flameproofing still to be done
Floor	4						
Windows	4						
Cupboard seats	3						
TOILETS							
Cleanliness Floor	1		Commode seat stored.	Sue Holman			New air hand driers and electric hot water supply
KITCHEN							
Hygiene	4		Food Hygiene Certificate – 14 persons have taken this and passed	Rosemary Walters			See Preparation of food policy
Floor	4		Needs regular washing	Sur Holman			Clean and sweep after use Floor has been scrubbed with bleach
Hot oven / hob	5		Oven gloves provided				See Preparation of food policy

Persons in kitchen	5		Control numbers in kitchen when cooking - max 4 and Max 6 when clearing away. No children - notice on door.	Rosemary Walters			See Preparation of food policy
Dishwasher	3		Clear Instructions provided				
Hot water	2		New boiler in place				
Kettles etc.	5		New December 2020	Anthony Bailey			Scalding risk
CORRIDOR							
Power Socket	5			Anthony Bailey			
GENERAL NOTES			PAT testing throughout Barn 4/8/2021				All PAT testing to be carried out in July 2022

Hazard Ratings

- 0 – No Risk
- 1 – Low Risk
- 2,3,4 Grades in between
- 5 – High Risk

Klargester Tank under patio at the Barn Centre.

It should be noted that the grey water from this tank is piped into the field behind the new graveyard where it disperses. This is legal under the current present legal guidance.

Should the graveyard be extended then the pipework in this area would need to be taken into consideration.

Policy in place Interruption of Usage i.e. Coronavirus 19 and being put into lockdown.

Fire Alarms are inspected at 6 monthly interval by Rypex Ltd and tested regularly by a designated volunteer.

5 Yearly Hard Wiring Test done in 2020 and Emergency Lighting Tested 2020 and rectification work carried out by Sullivan George.

Fire Risk Assessment has been carried out for 2021.

Ground floor Fire doors now have intumescent seals, 2 new door closers and safety notices applied.